## PRE-BID AUDITS

Request number	Facility	Steel Items to be Fabricated	Status of pre-bid Department Audit	Date Complete
1 2 3 4 5 6 7 8 9	Mitsubishi - Yokohama Mitsubishi - Hiroshima Mitsubishi - Kobe Kiewit Offshore Services Samsung - South Korea Nippon Steel/Tokyo Rope IHI Aichi Works IHI Yokohama Works IHI Kure-Shingu Works	Orthotropic Box Girger (OBG), Tower OBG, Tower OBG, Tower, Cross Beams Tower OBG, Tower, Cross Beams Wire, PPWS, Suspender Rope OBG Tower Tower (upper half)	Contingent pass Contingent pass Contingent pass Contingent pass Contingent pass Pass Pass Pass Contingent pass Contingent pass Contingent pass	11/26/2003 11/26/2003 11/26/2003 12/8/2003 2/12/2004 2/16/2004 3/8/2004 3/8/2004 3/8/2004

\* Legend on the second page

## Legend:

**"Pass"** Indicates that a facility currently appears to have all Facilities, Equipment, Personnel, and Procedures in place to conduct the work on the bid item indicated for this project.

"Fail" Indicates that a facility:

- a) Has not corrected all contingent items from a previous department audit for this project for the given bid item number, OR
- b) Appears to lack the ability to supply the bid item indicated within the parameters and/or schedule specified for this project.

"Contingent Pass" Reasonable plans are in place to make necessary changes to the facility prior to the start of work on this project.

All contingencies must be corrected as determined by a passing department re-audit prior to fabrication to

receive a status of "PASS."

For more detailed information regarding the results of the MFSQA and Department Audits please contact the audited facility directly. The Department will not release detailed results of audits to third parties.